

# THERMOGRAPHIC REPORT

Company | SUB BOARD  
Problem # | LOOSE TERMINAL


## IDENTIFICATION

Location Name | Location 10  
Equipment | MAIN SWITCH

## PROBLEM DESCRIPTION

LOOSE TERMINAL ON MAIN SWITCH

## THERMOGRAM



## TEMPERATURE MEASUREMENTS

Image Date	11/05/2004 2:06:42
Target Temperature	29.7 °C
Emissivity	0.98
Reflected Temp	28.0

## WEATHER

Air Temp	
Sky	
Wind Speed	
From	

Distance	Rated Load	Meas. Load	% Load
80cm	250 A	90A	

## MAINTENANCE ACTION

Description	Repaired by

## REPAIR PRIORITY

Subj. Rating	
Temp. Rating	

## REINSPECTION

Reinspected by	
Date	

## Comments

